RMT, Inc. 2025 E. Beltline Ave SE

Suite 402

Grand Rapids, MI 49546

TRANSMITTAL No. 00068

Phone: 616-975-5415 Fax: 616-975-1098

PROJECT: LEC Remediation Services

DATE: 3/21/2005

TO:

NJDEP

REF: PPU No. 8

Bureau of Federal Case Management Div. of Responsible Site Party Remed

CN028

Trenton, NJ 08625

Anthony Cinque ATTN:

WE ARE SENDING	ASSEMBLE REPORT OF THE PROPERTY OF	ENCONORED VIOLENCE CONTRACTOR CON
Shop Drawings	☐ Approval	Approved as Submitted
Letter	Your Use	Approved as Noted
Prints	☐ As Requested	Returned After Loan
Change Order	Review and Comment	Resubmit_
☐ Plans		☐ Submit
☐ Samples	SENT VIA:	Returned
☐ Specifications	☐ Attached	Returned for Corrections
Other: Project Progress Update No. 8	Separate Cover Via: Email 3/21/05	Due Date:

ITEM NO	. COPII	S DATE E	DOWN NOVIBER REV.	NO. DESCRIPTION	- ea State
01	1	3/18/2005		Project Progress Update No. 8	APP
02	1 .	3/18/2005		Project Progress Update No. 8 Photos	NEW

CC: S. Cipot, R. Alvey, F. Zizilia, J. Prendergast, G. Blyskun, J. Lewis C. Anderson, E. Schaub, C. Clavadetscher, J. Rheinhardt, RMT Project Team Signed: Chicatt Whiten Kor Nick Clevett Nick Clevett





To: gblyskun@dep.state.nj.us, jprendergast@dep.state.nj.us, Robert Alvey/R2/USEPA/US@EPA, Stephen Cipot/R2/USEPA/US@EPA, morrissoil@optonline.net, cristopher.anderson@polyone.com, Ernie.Schaub@polyone.com, james.lewis@polyone.com, Dan Oman <Dan.Oman@rmtinc.com>, Jeff Macri <Jeff.Macri@rmtinc.com>, Jim Dexter <Jim.Dexter@rmtinc.com>, Nakia Addison <Nakia.Addison@rmtinc.com>, Nicholas Clevett <Nicholas.Clevett@rmtinc.com>, Wally Kurzeja <Wally.Kurzeja@rmtinc.com>, jrheinhardt@whartonnj.com

Subject: LEC Source Reduction Progress Update No.@ 8

Please see attached Transmittal No. 00068. This is transmitting Progress Update No. 8 and the associated photo documentation.

Christy Whitford
Construction Management Project Assistant
RMT, Inc., Grand Rapids, MI
Ph. 616.975.5415 Ext. 1424
Fax 616.975.1098

Outgoing messages, along with any attachments, are scanned for viruses prior to sending.

NOTICE-- This email may contain confidential and privileged information for the sole use of the intended recipient. Any review or distribution by others is strictly prohibited. If you are not the intended recipient, please contact the sender

immediately and delete all copies. Trans 00068.pdf

L.E. CARPENTER & COMPANY ~ NJD002168748

BOROUGH OF WHARTON, MORRIS COUNTY, NEW JERSEY

SOURCE REDUCTION REMEDIAL PROJECT PROGRESS UPDATE NO. 8

Jon Rheinhardt, Borough of Wharton

Dan Oman, RMT Jim Dexter, RMT

Jeff Macri, RMT Dave Pratt, RMT

Walter Kurzeja, RMT

Nakia Addison, RMT

Date:

March 18, 2005

To:

Stephen Cipot, USEPA Anthony Cinque, NJDEP

From:

Nicholas J. Clevett, RMT

cc:

Robert Alvey, USEPA Frances Zizila, USEPA

John Prendergast, NJDEP George Blyskun, NJDEP Jim Lewis, LEC

Cris Anderson, LEC Ernie Schaub, LEC

Colin Clavadetscher, Morris County

.

Project No.:

00-06527.09

Subject:

SOURCE REDUCTION REMEDIAL ACTION

Project Progress Update No. 8

I. SOURCE REDUCTION REMEDIAL ACTIONS - THROUGH MARCH 11TH THROUGH MARCH 17TH 2005

- 1. Continued morning safety briefings (e.g., discussion of daily work scope and associated health and safety procedures)
- 2. Maintained air monitoring equipment (e.g., Weather Station, Miniram, PID, data loggers etc.) and air monitoring program (e.g., data log download, grab sampling)
- 3. Maintained all on-site heavy equipment (e.g., excavators, skid steer, off-road truck, screen, etc.)
- 4. Performed and documented daily inspections on the silt fence as outlined in the certified SESCP
- 5. Cleaned all paved areas with a skid steer broom attachment
- 6. Continued to load, transport and dispose of process wastes from the B-1 and B-2 areas. To date a total of 378 tons of process wastes have been removed from the site
- 7. Continued PCB impacted soil excavation and stockpiling of in those areas inside and outside [west] of the delineated wetland areas. To date, a total of 2,572 tons of PCB impacted soils have been excavated, loaded and transported off-site for disposal as non TSCA PCB wastes. When needed, cement kiln dust (CKD) was added to dry the excavated PCB soils prior to transportation and off-site disposal
- 8. Collected and submitted for analysis confirmatory samples (base and sidewall samples) for total PCBs in the PCB area as outlined in the RAWP documents (e.g., RAWP and regulatory response letters)
- 9. Initiated PCB area (wetland and non wetland area) backfilling activities
- 10. Completed setup of the batch plant and ancillary equipment to prepare slurry to facilitate the smear zone excavation within the saturated zone. The water pump was replaced due to mechanical failure and the Venturi maintenance performed due to clogging
- 11. Completed preparation of test slurry mix to ensure the correct mix and consistency prior to smear zone excavation activities

L.E. CARPENTER & COMPANY ~ NJD002168748

BOROUGH OF WHARTON, MORRIS COUNTY, NEW JERSEY

SOURCE REDUCTION REMEDIAL PROJECT PROGRESS UPDATE NO. 8

- 12. Initiated smear zone excavation utilizing the slurry mix. Once excavated, CKD was added to these materials to facilitate screening.
- 13. To date a total of 745 tons of CKD (32 loads) have been delivered to the site.
- II. PROPOSED SOURCE REDUCTION REMEDIAL ACTIONS MARCH 18TH THROUGH MARCH 24TH 2005
- 1. Continue to stockpile, load, transport and dispose of PCB impacted soils within permitted wetlands areas existing within the Wharton Enterprise property east of the LEC site, and conduct confirmatory sampling as required in the RAWP
- 2. Continue loading, transporting and disposing of process waste materials
- 3. Continue smear zone excavation activities



Photographic Log Progress Update No. 8

Client Name: Site Location: Project No.:

L.E. CARPENTER & COMPANY Wharton, Morris County, NJ 00-06527.09

Photo No. Date
1 3/17/05

Description

Cement Kiln Dust (CKD)



Photo No.

2 3/11/05

Description
Pumping mixed slurry into the excavation



Photographic Log Progress Update No. 8

Client Name: L.E. CARPENTER & COMPANY		Site Location:	Project No.:
		NY Wharton, Morris County,	NJ 00-06527.09
Photo No. Date 3/17/05			
Description Slurry mix curin excavation	g in the		
· .			
·			
d d			
			03/17/2005

Photo No.	Date
4	3/17/05
l Description	
Curing slurry	•
View looking ea	ıst
·	
ř	
	•



Photographic Log Progress Update No. 8

Client Name: L.E. CARPENTER & COMPANY			Site Location:	Project No.:	
		MPANY	Wharton, Morris County, NJ	00-06527.09	
Photo No.	Date 3/17/05				
Description Hardened slurr	ry				
	•				
		200			

Photo No		Date
6	3	/17/05

Description

Smear zone material ex-situ blending area (CKD, screening etc)

